



TECHNICAL BULLETIN

JetComp Shrink Sleeve Tips

When the shrink sleeve film seems hard to lift off the carrier sheet.

Sometimes, when you trim out a shrink sleeve, the trimming action itself causes the trimmed edge to “pinch together” with the liner. In this case, you need to slice into the edge of the shrink sleeve film with an Xacto blade As shown below. Once a corner is lifted, the sleeve will readily peel off the liner.

